

## -HS2CT 100- What's new in this version / Change Log

### Version 1.46

1. Improvement in the output level adjustment was not working properly in low level.
2. Fixed problem in the upgrade from version 1.44 and before.

### Version 1.44

1. Incremented the version number to maintain the same version of the other transmodulators.

### Version 1.39

1. Fixed QAM 16 problem.

### Version 1.37

1. Correction in output level.

### Version 1.35

1. Solved bugs with spectrum inversion.
2. Some problems with some DVB tables are fixed.
3. Fixed the problem of reset in the output services menu when is connected with the field meter.

### Version 1.26

1. Some problems with some DVB tables are fixed.
2. The DVBUS response time is improved.

### Version 1.09

1. Added the EPG support.
2. Added new option: Rename output services.

### Version 000A.0003

1. The problem with the option "Spectrum inversion" is corrected.
2. The channel 21 is assigned by default by making a "Values by default" to the transmodulator.

### Version 0008.0003

1. First version for the HS2CT 100 transmodulator.